




Test Pattern Update – Tacoma Dome

Installation

- Rainier Environmental Graphics installed June 10th
- TV test pattern used to demonstrate impact on multiple colors.




Condition

- Decal material held up well
 - Summer and Autumn weather
 - Proximity to I-5; Port of Tacoma
- Rainier Environmental Graphics
 - Correct installation of the decal
 - No water penetration

Cleanliness

- Noticeable film of dust
- More apparent on darker colors
- Dirt collected at seams where decal overlapped



Removal

- Removed 2 sq. ft. piece
- Decal tore; came off in several pieces
- Tacky texture remained on rubber roofing material



Recommendations

- Funding for cleaning every 6 months or at least twice a year
 - Estimate minimum \$150k per cleaning
 - Impact of repeated cleanings with chemicals / power washing not known
- Lock in and fund price for removal
 - Labor intensive / costly to remove
 - Current estimate does not include removal